	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
1	BRS	L1	1176	(EL electro?luminesce nt) near5 panel	USPA T	2002/08/07 15:26	
2	BRS	L2	63292	<pre>(back?up emergen42 au xiliary substitut\$3) same (light\$3 lamp tube)</pre>	USPA T	2002/08/07 16:23	
3	BRS	L3	113	1 and 2	USPA T	2002/08/07 15:55	
4	BRS	L4	35114	((EL electro?luminesc ent) near5 panel) LCD	1	2002/08/07 15:46	
5	BRS	L5	1754	2 and 4	USPA T	2002/08/07 16:53	
6	BRS	L6	55	5 and (315/\$7).ccls.	USPA T	2002/08/07 16:53	
7	BRS	L7	41	6 not 3	USPA T	2002/08/07 15:47	
8	BRS	L8	2080	2 and (315/\$7).ccls.	USPA T	2002/08/07 15:57	
9	BRS	L9	10138	panel and 2	USPA T	2002/08/07 15:56	
10	BRS	L10	11961	(LCD EL panel) and 2	USPA T	2002/08/07 17:07	
11	BRS	L11	378	10 and (315/\$7).ccls.	USPA T	2002/08/07 16:27	
12	BRS	L12	323	11 not (3 7)	USPA T	2002/08/07 15:59	
13	BRS	L13	196	12 and (AC battery)	USPA T	2002/08/07 16:19	
14	IS&R	L14	110	(315/88).CCLS.	USPA T	2002/08/07 16:37	
15	BRS	L15	42129	(back?up emergen42 au xiliary substitut\$3) and (battery)	USPA T	2002/08/07 16:46	
16	BRS	L16	3391	15 and 4	USPA T	2002/08/07 16:27	
17	BRS	L17	41	16 and (315/\$7).ccls.	USPA T	2002/08/07 16:27	
18	IS&R	L18	0	("14 not (3 7 17)").PN.	USPA T	2002/08/07 16:38	
19	BRS	L19	110	14 not (3 7 17)	USPA T	2002/08/07 16:55	
20	BRS	L20	173	(tuyet near3 vo).xa.	USPA T	2002/08/07 16:45	
21	BRS	L21	49516	(back?up emergen\$2 au xiliary substitut\$3) and (battery)	USPA T	2002/08/07	
22	BRS	L22	6	20 and 21	USPA T	2002/08/07 16:50	

	Туре	L #	Hits	Search Text	DBs	Time S	tamp	Comment s
23	BRS	L23	6075	<pre>back?up same (battery voltage powe r)</pre>	USPA T	2002/08 16:53	3/07	
24	BRS	L24	667	23 and 4	USPA T	2002/08 16:54	3/07	
25	BRS	L25	0	24 and (315/\$7).ccls.	USPA T	2002/08 17:06	3/07	
26	BRS	L26	0	14 not (3 7 17 19)	USPA T	2002/08 16:55	3/07	
27	BRS	L27	662	24 not (3 7 17 19)	USPA T	2002/08 17:07	3/07	
28	BRS	L28	933	21 and (315/\$7).ccls.	USPA T	2002/08 17:06	3/07	
29	BRS	L29	214	(LCD EL panel) and 28	USPA T	2002/08 17:07	3/07	
30	BRS	L30	171	29 not (3 7 17 19)	USPA T	2002/08 17:33	3/07	
31	BRS	L31	1	"5914571".PN.	USPA T	2002/08 17:19	3/07	
32	BRS	L32	1	"5757144".PN.	USPA T	2002/08 17:19	1/07	
33	BRS	L33	1	"5611163".PN.	USPA T	2002/08 17:19	/07	
34	BRS	L34	1	"5581161".PN.	USPA T	2002/08 17:20	/07	
35	BRS	L35	1	"5548189".PN.	USPA T	2002/08 17:20	/07	
36	BRS	L36	1	"5526251".PN.	USPA T	2002/08 17:21	/07	
37	BRS	L37	1	"5521467".PN.	USPA T	2002/08 17:21	/07	
38	BRS	L38	1	"5512801".PN.	USPA T	2002/08 17:22	/07	
39	BRS	L39	1	"5512801".PN.	USPA T	2002/08 17:22	/07	
40	BRS	L40	1	"5461286".PN.	USPA T	2002/08 17:22	/07	
41	BRS	L41	1	"5408162".PN.	USPA T	2002/08 17:22	/07	
42	BRS	L42	58	(315/291).ccls. and 21	USPA T	2002/08 17:39	/07	
43	BRS	L43	35	(315/169.?).ccls. and 21	USPA T	2002/08 17:43	/07	
44	BRS	L44	45597	(interrupt\$4 fail\$4) near6 power	USPA T	2002/08 17:42	/07	
45	BRS	L45	15226	44 and battery	USPA T	2002/08 17:43	/07	

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment s
46	BRS	L46	39	((315/169.?).ccls. (3 15/291).ccls. (315/20 9A).ccls. (315/200R). ccls.) and 45		2002/08/07 17:56	
47	IS&R	L47	106	(307/23).CCLS.	USPA T	2002/08/07 17:56	